

# D2 class Instruction Diagrams 2

## Platform / Footplate forming

'A' denotes areas that need to be annealed

curved shape forms L strake  
soldered at rear edge of raised band



